

Table of Contents

1	Introduction.....	13
	1.1 Watershed Description.....	13
	1.1.1 Overview.....	13
	1.1.2 Geology.....	15
	1.1.3 Hydrology.....	16
	1.1.4 Historical and Present Land Use.....	17
	1.2 Impaired Waters.....	18
	1.2.1 Water Quality Standards and 303(d) Listing.....	18
	1.2.2 Pollutants of Concern.....	20
	1.2.3 Overview of TMDL Methodology.....	26
	1.2.4 Impacted Species.....	29
2	Watershed Partnerships and Efforts.....	31
	2.1 Stakeholders.....	31
	2.2 Outreach Activities and Technical Assistance.....	31
	2.3 Monitoring Program.....	32
3	Water Quality Analysis and Characterization.....	38
	3.1 Water Quality Data Analysis Review.....	38
	3.2 Past Investigations/Mine Inventories/Site Assessments.....	39
	3.3 Evaluation of Physical Habitat.....	40
4	Best Management Practices.....	41
	4.1 Overview.....	41
	4.2 Mining BMP.....	42
	4.2.1 Surface and Subsurface Hydrologic Controls.....	42
	4.2.1.1 Waste Rock/Tailings Consolidation/Removal and Stabilization.....	42
	4.2.1.2 Waste Rock/Tailings Regrading.....	42
	4.2.1.3 Waste Rock/Tailings Capping.....	42
	4.2.1.4 Vegetation.....	42
	4.2.1.5 Bulkhead Seals and Plugs.....	43
	4.2.1.6 Diversion Ditches.....	43
	4.2.2 Passive Water Treatment Technologies.....	43
	4.2.2.1 Chemical Amendment.....	43
	4.2.2.2 Anoxic Limestone Drains.....	43
	4.2.2.3 Aeration and Settling Ponds.....	43
	4.2.2.4 Sulfate Reducing Wetlands.....	43
5	Watershed Management Actions, Strategy and Remediation.....	44
	5.1 Snake River.....	45
	5.2 Deer Creek.....	52
	5.3 Sts. John Creek.....	55
	5.4 Peru Creek.....	58

5.4.1	Pennsylvania Mine.....	63
5.4.2	Cinnamon Gulch.....	67
5.4.3	Warden Gulch.....	70
5.5	Project Prioritization.....	72
6	Pollutant Reductions.....	78
6.1	Pennsylvania Mine.....	78
6.2	Sts. John Mine.....	80
6.3	Jumbo Mine.....	81
6.4	Blanche Mine.....	81
6.5	Warden Gulch Mine.....	82
6.6	Delaware Mine.....	82
6.7	Brittle Silver Mine.....	83
6.8	Silver Spoon Mine.....	83
6.9	Channelize Cinnamon Gulch.....	84
6.10	East of Montezuma.....	84
6.11	Pollutant Characterization and Removal Impacts.....	85
6.11.1	Ambient Conditions	85
6.11.2	Remediation Beneficial Impacts.....	87
6.11.2.1	Snake River Above Peru Creek.....	88
6.11.2.2	Peru Creek.....	89
6.11.2.3	Snake River below Peru Creek.....	90
6.11.2.4	Snake River above the NFSR.....	91
6.11.2.5	Snake River below the NFSR.....	92
6.12	Implementation Schedule/Milestones/Criteria.....	94
7	Overview of Applicable Funding Sources.....	96
7.1	Clean Water Act § 319.....	96
7.2	Brownsfields Program.....	97
7.3	USEPA Targeted Watershed Grant Program.....	98
7.4	Ecosystem Protection Regional Geographic Initiative.....	98
7.5	Colorado Healthy Rivers Fund.....	99
7.6	USEPA Community Action for a Renewed Environment Grant	99
7.7	Other Funding Sources.....	99
8	Acknowledgements.....	100

References

List of Figures

Figure 1	Snake River Watershed Map.....	14
Figure 2	Seasonal and Multiyear Streamflow Variations, Snake River Near Keystone (SW-082)	17

Figure 2a	Historical Water-Quality Monitoring Stations in the Snake River Watershed.....	33
Figure 2b	Selected Monitoring Sites for Future Monitoring	38
Figure 3	Cashier Mine.....	45
Figure 4	Upper Snake River Waste-Rock Pile.....	46
Figure 5	Upper Snake River Disturbed Lands.....	46
Figure 6	Blanche Mine Adit.....	47
Figure 7	Blanche Mine Waste Rock.....	47
Figure 8	Upper Snake River Leaking Adit.....	47
Figure 9	Upper Snake River Waste Rock.....	47
Figure 10	North Superior Mine.....	48
Figure 11	South Superior Mine.....	48
Figure 12	Burke-Martin Mine Tailings.....	49
Figure 13	Burke-Martin Mine Adit Flow/Waste Rock.....	49
Figure 14	Mine North of Burke-Martin.....	49
Figure 15	Tailings below Montezuma.....	49
Figure 16	Adit Flow/Waste Rock Mine Below Montezuma.....	49
Figure 17	Lower End of Tailings below Montezuma.....	50
Figure 18	Flow from Contaminated Area Below Montezuma.....	50
Figure 19	New York Mine Adit Flow.....	50
Figure 20	New York Mine Adit Flow to Road.....	50
Figure 21	Waste Rock, Mine East of Montezuma.....	51
Figure 22	Adit Flow, Mine East of Montezuma.....	51
Figure 23	Morgan Mine Adit Flow.....	51

Figure 24	Morgan Mine Waste Rock.....	51
Figure 25	East Deer Creek Draining Adit.....	52
Figure 26	East Deer Creek Waste Rock.....	52
Figure 27	Radical Mine Adit.....	52
Figure 28	Radical Mine Waste Rock.....	52
Figure 29	Lower Chatauqua Adit Flow.....	53
Figure 30	Lower Chatauqua Waste Rock.....	53
Figure 31	Deer Creek Draining Adit.....	53
Figure 32	Deer Creek Waste-Rock Flow.....	53
Figure 33	Deer Creek Adit Flow Entering Snake River.....	54
Figure 34	Upper Sts. John Waste Rock.....	55
Figure 35	Wild Irishman Adit Flow.....	55
Figure 36	Wild Irishman Waste Rock.....	55
Figure 37	Mine North of Wild Irishman Adit Flow.....	55
Figure 38	Sts. John Mine Adit Flow.....	56
Figure 39	Sts John Adit Flow North.....	56
Figure 40	Sts John Adit Flow South.....	56
Figure 41	Sts John Adit Flow North near Stream.....	57
Figure 42	Sts John Mine Seepage from Stream.....	57
Figure 43	Tailings at Sts John Mine.....	57
Figure 44	Marlin Mine Adit Flow.....	57
Figure 45	Sts John Meadow with Tailings.....	57
Figure 46	Horseshoe Basin Draining Adit.....	58
Figure 47	Horseshoe Basin Waste Rock.....	58

Figure 48	Peru Creek Flow by Waste Rock Pile.....	58
Figure 49	Paymaster Mine Waste Rock.....	58
Figure 50	Paymaster Mine Open Shaft.....	58
Figure 51	Falls Gulch Flow Channel.....	59
Figure 52	Peru Creek Waste Rock by Road Crossing.....	59
Figure 53	Open Shaft near Road Stream Crossing.....	59
Figure 54	Shoe Basin Mine Draining Adit.....	60
Figure 55	Peru Creek Waste Rock in Avalanche Chute	60
Figure 56	Pennsylvania Mine Adit Flow Entering Peru Creek.....	60
Figure 57	Pennsylvania Mine Waste Rock.....	60
Figure 58	Pennsylvania Mine Level C Waste Rock.....	61
Figure 59	Pennsylvania Mine Adit Flow.....	61
Figure 60	Peru Creek Flowing Adit Northern Slope.....	61
Figure 61	Peru Creek Waste Rock Northern Slope	61
Figure 62	Silver Lode Mine Adit.....	61
Figure 63	Flowing Adit West of Maid-of-Orleans Mine.....	61
Figure 64	Jumbo Mine Draining Adit.....	62
Figure 65	Jumbo Mine Waste Rock.....	62
Figure 66	Pennsylvania Mine Adit.....	63
Figure 67	Pennsylvania Mine Adit in 2007.....	63
Figure 68	Pennsylvania Mine Level F Waste Rock.....	63
Figure 69	Pennsylvania Mine Tailings Area.....	64
Figure 70	Pennsylvania Mine Level C Waste Rock.....	65

Figure 71	Pennsylvania Mine Level F Waste Rock.....	65
Figure 72	Silver Spoon Draining Adit.....	67
Figure 73	Silver Spoon Waste Rock.....	67
Figure 74	Rich Ore Group Draining Adit.....	67
Figure 75	Upper Cinnamon Gulch Waste Rock.....	67
Figure 76	Upper Delaware Mine Adit Flow.....	68
Figure 77	Upper Delaware Mine Waste Rock.....	68
Figure 78	Delaware Mine Waste Rock.....	68
Figure 79	Delaware Mine Draining Adit.....	68
Figure 80	Little Nell Mine Open Adit.....	69
Figure 81	Cinnamon Gulch flowing down road.....	69
Figure 82	Brittle Silver Waste Rock.....	69
Figure 83	Allen Emory Mine Waste Rock.....	70
Figure 84	Warden Gulch Waste Rock.....	71
Figure 85	Warden Gulch South Slope Waste Rock.....	71
Figure 86	Warden Gulch Draining Adit.....	71
Figure 87	Warden Gulch Waste Rock.....	71
Figure 88	Snake River Flows and Zinc-Concentration Profiles.....	87
Figure 89	D-Zinc Concentration Reductions Resulting from Remedial Actions, Snake River above Peru Creek (SW-047).....	89
Figure 90	D-Zinc Concentration Reductions Resulting from Remedial Actions, Peru Creek near Confluence with the Snake River (SW-049).....	90
Figure 91	D-Zinc Concentration Reductions Resulting from Remedial Actions, Snake River below	

	Peru Creek (SW-050).....	91
Figure 92	D-Zinc Concentration Reductions Resulting from Remedial Actions, Snake River above North Fork Snake River (SW-117)	92
Figure 93	D-Zinc Concentration Reductions Resulting from Remedial Actions, Snake River below North Fork Snake River (USGS Gage near Keystone, SW-082).....	93

List of Tables

Table 1	Designated Uses and Impairment Status for Segments 6 and 7, Mainstem of the Snake River, Saints John Creek and Peru Creek	19
Table 2	Permitted Dischargers.....	20
Table 3	Sources of Water-Quality Data for 303(d) Listed Stream Segments in the Snake River Watershed.....	20
Table 4	Current TVS and Ambient Water Quality for 303(d) Listed Segments of the Snake River at Sites Above Deer Creek.....	21
Table 5	Current TVS and Ambient Water Quality for 303(d) Listed Segments of the Snake River above Peru Creek.....	22
Table 6	Current TVS and Ambient Water Quality for 303(d) Listed Segments of Peru Creek.....	22
Table 7	Current TVS and Ambient Water Quality for 303(d) Listed Segments of the Snake River at Sites Below Peru Creek.....	23
Table 8	Current TVS and Ambient Water Quality for tributaries of the Snake River and Peru Creek.....	23
Table 9	Current TVS and Ambient Water Quality for 303(d) Listed Segments of the Snake River at Site above the North Fork Snake River Confluence.....	24
Table 10	Current TVS and Ambient Water Quality for 303(d) Listed Segments of the Snake River at Site Below North Fork Snake River	25

Table 11	Annual Cadmium, Copper, Lead and Zinc Total Maximum Daily Load Contributions for the Snake River and Peru Creek tributaries.....	25
Table 12	Zinc Total Maximum Daily Load and Load Allocations for Segment 7, Peru Creek at Mouth.....	27
Table 13	Zinc Total Maximum Daily Load Allocations for the Portion of Segment 6, the Snake River above Peru Creek.....	27
Table 14	Zinc Total Maximum Daily Load Allocations for the upper part of Segment 6, the Snake River below Peru Creek.....	28
Table 15	Zinc Total Maximum Daily Load Allocations for the upper part of Segment 6, the Snake River below Peru Creek and Above North Fork Snake River...	28
Table 16	Zinc Total Maximum Daily Load Allocations for the upper part of Segment 6, the Snake River below North Fork Snake River.....	29
Table 17	Recent Monitoring Sites, Snake River Watershed.....	34
Table 18	Snake River Watershed Prioritized Mine-Related Remediation Projects.....	73
Table 19	Streamflow and Water-Quality Conditions at Selected Monitoring Sites, Snake River Watershed.....	86
Table 20	Summary of Estimated Zinc-Loads Reductions (lbs/y)..	88

Appendices

Appendix A

Stream Drainage Basin Descriptions

- Upper Snake River
- Snake River below Deer Creek
- Deer Creek
- Saints John Creek
- Peru Creek
- Cinnamon Gulch
- Warden Gulch
- Grizzly Gulch

Appendix B
Geology Map
Hydrothermal Alteration Map

Appendix C
Snake River Watershed Task Force Membership (SRWTF)

Appendix D
Past Research Activities in Snake River Watershed

Appendix E
Snake River Visual Evaluation (Walsh, 2007 Memorandum)

Appendix F
Snake River TMDL Final Document (WQCD, 2007)

Appendix G
Supplemental Information, Zinc Concentration/Loads Reduction Assessment
(Steele, 2008, written communication, 11/22/08)

List of Acronyms

ARD	Acid Rock Drainage
BRWG	Blue River Watershed Group
BMP	Best Management Practices
CDOW	Colorado Division of Wildlife
CDPHE	Colorado Department of Public Health and Environment
CDRMS	Colorado Department of Reclamation, Mining and Safety
CWA	Clean Water Act
D-Zinc	Dissolved Zinc
GPM	Gallons Per Minute
MOS	Margin of Safety
NFSR	North Fork Snake River
NPDES	National Pollutant Discharge Elimination System
NWCCOG	Northwest Colorado Council of Governments
QSP	Quartz-Sericite-Pyrite
SRWTF	Snake River Watershed Task Force
TMDL	Total Maximum Daily Load
TU	Trout Unlimited
TVS	Table Value Standards
USEPA	United States Environmental Protection Agency
USFWS	United States Fish and Wildlife Service
USGS	United States Geological Service
WLA	Waste Load Allocation
WQCD	Water Quality Control Division